



Sanitary Sewer Overflow Annual Report

Division of Surface Water

Date: 03/08/2024		
Facility Name: Zanesville WWTP		
Ohio NPDES Permit Number: 0PE00000*TD		
Period Covered by Report: 01/01/2023 - 12/31/2023		
Contact Person: William Randles	Title: Superintendent	
Mailing Address: 1730 Moxahala Avenue		
City: Zanesville	State: OH	Zip Code: 43701
Country: USA		
Sanitary Sewer Overflows Spreadsheet(attachment) :		
Water In Basement Occurrences Spreadsheet(attachment) : SSO Monitoring Report 2023.xlsxm		
Narrative analysis of WIB patterns by location, frequency and cause: The 2 WIB's occurred due to roots and grease build up. These two areas have been cleaned and no longer are causing any issues.		

ADDITIONAL INFORMATION

Please add any additional comments or attachments below.

Certification

I certify under penalty of law that I have personally examined and am familiar with the information in this report and all attachments. Based on my inquiry of those persons immediately responsible for obtaining the information contained in the report, I believe that the information is true, accurate, and complete.

Name: William Randles	Title: Deputy Waste Water Superintendent
Signature(Electronically submitted by): William Randles (User ID: smokenbandit9)	Submission Date: 03/11/2024